




CODE	Form	w	l	l ₁	l ₂	b
G220-03-028-075	A	28	75	15	45	-
G220-03-028-100	A	28	100	25	50	-
G220-03-028-125	A	28	125	25	75	-
G220-03-028-150	A	28	150	25	100	-
G220-03-038-075	A	38	75	15	45	-
G220-03-038-100	A	38	100	25	50	-
G220-03-038-125	A	38	125	25	75	-
G220-03-038-150	A	38	150	25	100	-
G220-03-048-075	A	48	75	15	45	-
G220-03-048-100	A	48	100	25	50	-
G220-03-048-125	A	48	125	25	75	-
G220-03-048-150	A	48	150	25	100	-
G220-03-048-200	A	48	200	50	100	-
G220-03-058-075	A	58	75	15	45	-
G220-03-058-100	A	58	100	25	50	-
G220-03-058-125	A	58	125	25	75	-
G220-03-058-150	A	58	150	25	100	-
G220-03-058-200	A	58	200	50	100	-
G220-03-075-075	A	75	75	15	45	-
G220-03-075-100	A	75	100	25	50	-
G220-03-075-125	A	75	125	25	75	-
G220-03-075-150	A	75	150	25	100	-
G220-03-075-200	C	75	200	25	75	-
G220-03-100-100	B	100	100	25	50	50
G220-03-100-125	B	100	125	25	75	50
G220-03-100-150	B	100	150	25	100	50
G220-03-100-200	B	100	200	25	150	50
G220-03-100-250	B	100	250	25	200	50
G220-03-125-150	B	125	150	25	100	50
G220-03-125-200	B	125	200	25	150	50
G220-03-125-250	B	125	250	25	200	50
G220-03-150-150	B	150	150	25	100	100
G220-03-150-200	B	150	200	25	150	100